
Written by Hans Summers Sunday, 28 June 2009 03:41 -



L4 at maximum inductance. Not much going on.



Decreasing the inductance of L4, signals suddenly snap in at about 66 and 86MHz (86MHz might

Written by Hans Summers Sunday, 28 June 2009 03:41 -

