


## 30m QRSS beacon: QRV2: reports

Written by Hans Summers

Saturday, 13 June 2009 06:01 - Last Updated Saturday, 13 June 2009 06:38


---



### Week 1: 25-Aug-04 - 31-Aug-04

G3GKI, LA5VNA, DF5SF, PA1SDB, DL2WRJ, ON5SL, DL6JAN. No copy: ZL1BPU, VK6DI, G4KKI

[Read more...](#)



### Week 2: 01-Sep-04 - 07-Sep-04

SM6LKM, DL6JAN, PA1SDB, DF5SF. No copy: ON6RR, K7HKL, G4KKI

[Read more...](#)



### 08-SEP-04: QRT


A [strap-on crystal heater from DB6NT](#) was fitted to improve frequency stability by

### 09-SEP-04 - 12-SEP-04: QRV but no luck

No reports were received. It appeared to me also that the antenna tuning was "wierd": normally the null is

### 18-SEP-04: QRV again!

This time, the ATU tuning "felt" right. Power readings and SWR were normal. However there were still N



### 25-SEP-04 - 29-Sep-04

DL6NL, DL2WRJ, LA5VNA, DF5SF, PA1SDB, OE5EEP. No copy: VK6DI, ON6RR, ON5EX

[Read more...](#)



### 30-SEP-04 - 07-OCT-04

PA1SDB, OE5EEP, ON4LP, ON5SL. No copy: VK6DI, G3GKI


[Read more...](#)

## 30m QRSS beacon: QRV2: reports

Written by Hans Summers

Saturday, 13 June 2009 06:01 - Last Updated Saturday, 13 June 2009 06:38

---



[Read more](#) ~~08406604 OE1E DC104~~ 5VNA. No copy: G3GKI